Oil Field Environmental Incident Summary

Responsible Party: SM ENERGY COMPANY **Well Operator:** SM ENERGY COMPANY

Well Name: ANDERSON 10-13

Field Name: CROFF Well File #: 11624

Date Incident:12/23/2014Time Incident:16:30Facility ID Number:County:MCKENZIETwp:149Rng:96Sec:13Qtr:

Location Description:

Submitted By: Luke Studer Received By:

Contact Person: LUke Studer

PO BOX 7168

BILLINGS, MT 59103-7168

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No **Units** Recovered Units Spilled Followup **Units** Oil 0 barrels **Brine** 0 barrels Other 10 **Barrels Barrels** barrels

Description of Other Released Contaminant:

Illegal dumping of 10 yards cuttings on location

Inspected: Written Report Received: 3/9/2016 Clean Up Concluded: 12/23/2014

Risk Evaluation:

minimum

Areal Extent:

10-40

Potential Environmental Impacts:

none

Action Taken or Planned:

Scraped up cuttings and hauled to nuverra arnegaard facility

Wastes Disposal Location: Nuverra

Agencies Involved:

Updates

Date: 12/26/2014 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an illegal dumping, remained on the constructed well site according to the report. NDIC retains oversight.